

ALL POLES WILL NEED TO
BE STENCILED
897/1 THROUGH 897/14
REMOVE P

897/P13
40'CL3
NEEDS STENCIL

897/P11
40'CL3
NEEDS STENCIL

897/P12
40'CL3
NEEDS STENCIL

897/P12
37.5(C)